



Before



After

## SCORE


The following score represent a normalized sum of needed improvements for each site. The higher the score, the greater the need.

### TRANSIT USE




100%

### CONNECTIVITY/ ACCESSIBILITY



87%

### AMENITIES



81%

## Recommendations for this Stop

- Work with property owner for ADA improvements
- Consider crosswalk for improved connectivity
- Install amenities, such as ramps, shelter, and seating

# \$11,150

Estimated Cost :  
(Materials Only)